



CITRICUT GEL

CITRUS-BASED WETWASH / DEGREASER CLINGS TO VERTICAL & OVERHEAD SURFACES

When using any NUVITE product, please refer to appropriate procedures and recommendations for use and equipment, or contact a NUVITE technician for more information, unique applications and special requirements.

HEAVY-DUTY CLEANING/GEAR, WHEEL WELLS, FLAPS, COWLINGS



1. Use full strength concentrate.
2. Allow to soak 5-10 minutes.
3. DO NOT allow soaked area to completely dry.
4. Rinse with high pressure water.

VERTICAL OR OVERHEAD SURFACES



1. Spray full strength on surface with low pressure spray.
2. Allow to soak 5-10 minutes.

WETWASH

1. Depending on soil conditions and cleaning frequency, dilute 1:2-1:8 with water.
2. Apply to aircraft surfaces by spray or mop application.
3. Agitate immediately to loosen soil and rinse with water.