



85 JETSON LANE, CENTRAL ISLIP, NEW YORK 11722

516.935.4000 FAX 516.935.4039

WWW.NUVITECHEMICAL.COM

WWW.UNIVERSALPHOTONICS.COM

TECHNICAL DATA

NUPOWER II

Waterless Cleaning Dry Wash/Polish Paint Protectant

Nuvite NuPower II is an extraordinary product for ongoing care of painted or polished metal surfaces. It is easily applied with a wipe-on, wipe-off procedure with pad applicators or by hand in all types of humidity conditions. NuPower II is a high technology formulation that offers cleaning power, a bright shine, and a protective barrier coating against surface oxidation that also protects against ultraviolet deterioration. Because NuPower II is so easy and fast to use, it offers significant savings in labor and retains maximum appearance protection and performance in both fleet and heavy service situations.

- Exceptional Soil Dispersion Power
- Removes Surface Oxidation from Paint and Metal Surfaces
- Easy Wipe On, Let Dry, Wipe Off to a Clean, Bright Surface.
- Adds a Beautiful Gloss Appearance with an Effective Ultraviolet Protectant Coating on Both Painted and Metal Surfaces
- Easy Application in All Climates
- Preserves and Protects Substrate From Further Oxidation and Leaves a Protective Coating Against U/V and Atmospheric Corrosion/Salt Spray/Pollution Without Color Change
- Offers Superior Cleaning Results and Protection With Fewer Man-Hours and a Low Material Requirement
- Safe to All Aircraft Components; conforms to Airframe OEM standards and specifications

PHYSICAL CHARACTERISTICS

- **Appearance:** Tan, semi-viscous liquid
- **Odor:** Mild
- **pH:** 11.5 – 11.8 @ 25°C
- **Solubility:** Dispersible in water
- **Specific Gravity:** 0.940 @ 25°C

INSTRUCTIONS FOR USE

For Normal or Lightly Soiled Surface Conditions: Apply NuPower II “as is” by hand, spray or mop head to small areas at a time. Agitate area evenly with wet material. Allow to fully dry (usually no more than 5-10 minutes even in the highest humidity conditions). Remove by buffing out with clean mop head or dry terry or similar towel to shine.

For Heavily Soiled Surface Conditions: For grease, oil, hydraulic oil buildup, it is recommended that the area be wiped down or wet washed with Nuvite **CitriCut** or **SS-9-3** degreasing cleaners prior to the use of NuPower II, and then proceed as above.

When using Nuvite products, please use recommended procedures and equipment. For further product information, and technical support, consult a Nuvite Representative at 800.394.8351



85 JETSON LANE, CENTRAL ISLIP, NEW YORK 11722

516.935.4000 FAX 516.935.4039

WWW.NUVITECHEMICAL.COM

WWW.UNIVERSALPHOTONICS.COM

HEALTH AND SAFETY

Nuvite NuPower II contains petroleum distillates. Users should wear gloves and goggles as standard safety procedures. Refer to Safety Data Sheet for further health and safety information.

AVAILABILITY

NuPower II is available in 1 & 4 oz, 1 quart, 1 & 5 Gallon and 55 Gallon Drums

This technical data sheet is offered in good faith without warranty or representation solely for the buyer's use in the evaluation of this product. It is the responsibility of the buyer and end user to determine the data and safety information with respect to applicable laws, regulations, and the fitness & character of this product prior to full scale use. UNIVERSAL PHOTONICS and or NUVITE CHEMICAL COMPOUNDS (seller) assumes no legal liability for any injury, accident, loss, or damage through the use of this product of which such uses are beyond seller's control.nupowerII.10.16.td